V fiel



## BSI-Inspectorate America 178 Mortland Road Searsport, Maine 04974 (207)548-6440

## QUALITY CERTIFICATE

Vessel Customer SHORE TANK NO. 1

SPRAGUE

Operation ANALYSIS

Port Date

Terminal

SEARSPORT, MAINE

March 21, 2003

SPRAGUE

Report

SP/03/0345

Reference

Sample # 287167

Name of material being tested Description of sample source Samples Drawn by (company) Samples Tested by (company)

## **NO. 6 FUEL OIL 1.5%**

EX. SHORE TANK NO. 1 AFTER DISCHARGE OF FLORIDA
INSPECTORATE
INSPECTORATE

Tests being Performed	Test method	Minimum Maximum	Sample Source
GRAVITY, API @ 60 F	ASTM D 4052		12.0
SULPHUR, % WT.	ASTM D 4294		1.473
	÷		
and the second			